



THAI KAJIMA CO., LTD.

Architects Engineers Contractors Developers

19th FL., RAMALAND BLDG., 952 RAMA IV ROAD,
BANGRAK, BANGKOK 10500, THAILAND
NATIONAL TEL : 0-2632-9300 FAX : 0-2632-9312
INTERNATIONAL TEL : + 66-2632-9300 FAX : + 66-2632-9312

Ref: MP-POL-006/2025

Date: 12 June 2025

Dear Employees, Contractors, Suppliers,

Subject: PROHIBITION ON ORDERING STEEL PRODUCED USING INDUCTION FURNACE (IF) METHOD

We would like to formally announce that effective immediately, our Company will prohibit the procurement of steel manufactured using the Induction Furnace (IF) method from any supplier.

This decision follows an investigation into the collapse of the State Audit Office (SAO) building in Bangkok, which was triggered by an earthquake. Findings have revealed that substandard steel, specifically produced using Induction Furnaces (IF), played a significant role in the collapse. Based on these concerns, and the results of testing conducted by the Iron and Steel Institute of Thailand, **IF method steel has been confirmed to fail industry standards and will no longer be accepted in our operations.**

We appreciate the cooperation of all parties in adhering to this directive. Any purchase orders involving IF – method steel will be cancelled or rejected moving forward. Please ensure all procurement processes, as well as subcontractor and supplier engagements, reflect this update.

Thank you for your attention and continued commitment to quality and compliance.

THAI KAJIMA CO., LTD.

Tatsuya Ashida
President.



THAI KAJIMA CO., LTD.
Architects Engineers Contractors Developers

19th FL., RAMALAND BLDG., 952 RAMA IV ROAD,
BANGRAK, BANGKOK 10500, THAILAND
NATIONAL TEL : 0-2632-9300 FAX : 0-2632-9312
INTERNATIONAL TEL : + 66-2632-9300 FAX : + 66-2632-9312

ที่ MP-POL-006/2025

วันที่ 12 มิถุนายน 2568

เรื่อง ห้ามจัดซื้อเหล็กที่ผลิตโดยใช้เตาเหนี่ยวนำ (IF) มาใช้ในโครงการงานก่อสร้างของบริษัท

เรียน พนักงาน, ผู้รับเหมาช่วง และผู้จัดจำหน่ายทุกท่าน

ด้วยเหตุผลด้านมาตรฐานและความปลอดภัย บริษัทขอประกาศห้ามจัดหาและนำเหล็กที่ผลิตโดยเตาเหนี่ยวนำ (Induction Furnace – IF) จากผู้จัดจำหน่ายทุกแห่งมาใช้ในการก่อสร้างโครงการต่าง ๆ ของบริษัท โดยมีผลบังคับใช้ทันที

ทั้งนี้ ด้วยเหตุผลจากการสอบสวนเหตุการณ์ถล่มของอาคารสำนักงานการตรวจเงินแผ่นดิน (SAO) ในกรุงเทพฯ ซึ่งได้รับผลกระทบจากแผ่นดินไหว จากการตรวจสอบพบว่ามีการใช้เหล็กที่ไม่ได้มาตรฐาน โดยเฉพาะเหล็กที่ผลิตโดยเตาเหนี่ยวนำ (IF) มีส่วนเกี่ยวข้องอย่างมีนัยสำคัญกับความเสียหายที่เกิดขึ้นในครั้งนี้ ผลการทดสอบจากสถาบันเหล็กและเหล็กกล้าแห่งประเทศไทย ยืนยันว่าเหล็กประเภทนี้ไม่เป็นไปตามมาตรฐานอุตสาหกรรม ดังนั้น บริษัทจึงขอประกาศ ห้ามใช้เหล็กที่ผลิตโดยเตาเหนี่ยวนำ (IF) ในโครงการก่อสร้างต่าง ๆ ทั้งหมดของบริษัทต่อไป

บริษัทขอขอบคุณทุกฝ่ายที่ให้ความร่วมมือในการปฏิบัติตามมาตรการนี้ เอกสารการสั่งซื้อที่เกี่ยวข้องกับเหล็กที่ใช้เตาเหนี่ยวนำ (IF) จะต้องถูกยกเลิกหรือปฏิเสธในทุกกรณี และตรวจสอบให้แน่ใจว่ากระบวนการจัดซื้อทั้งหมดรวมถึงข้อตกลงกับผู้รับเหมาช่วงหรือผู้จัดจำหน่าย ต้องปรับแก้ไขให้เป็นไปตามมาตรการดังกล่าวข้างนี้

บริษัทขอขอบคุณทุกฝ่ายในความร่วมมือปฏิบัติตามแนวทางที่กำหนด เพื่อรักษามาตรฐานด้านคุณภาพในการก่อสร้างของบริษัท.

ขอแสดงความนับถือ

บริษัท ไทยคاجิมา จำกัด

มร. ทัทสุยะ อะซิดะ

ประธานบริษัท ฯ